

*Shanket Shah*

Ref. No. Cert/CH/01/05-23

May 8, 2023

To,  
The Hon. Secretary,  
The General Education Institute,  
Chubildas High School, Opposite Wanmali Hall,  
Chhabildas Road, Dadar (W), Dadar,  
Mumbai - 400028.

SUB.: Structural Stability certificate.

Respected Sir,

I do hereby state that the need-based repair works of the fire damaged part been carried out as per our instructions & supervision. Structural alterations of any kind were neither proposed nor approved. The workmanship and materials used are of good quality and the works carried out are to our satisfaction. Hence I hereby certify that the school building structure shall remain safe & stable for its intended use.

The following items of work have been executed -

All the necessary need-based patchwork repairs near the west end (i.e. above the second floor which was damaged due to fire) including plastering, waterproofing & replacing the damaged roofing sheets have been completed.

I further state that-

1. This letter is valid only for the repair works that were carried out under our instructions & guidance and does not include areas of the building that were not attended by us.
2. Our firm remains absolved of any responsibilities/ consequences which may arise during the defects liability period and thereafter due to any of the following damages/ abuses inflicted by the clients/ occupants and by any other agencies.
  - > Tampering/ chasing of the framework of both internal & external facades including the repaired areas.
  - > Overloading of floors.

